

بنوع الله الرحمن الرحيم

OMAN AVIATION SERVICES CO. S.A.O.  
C.R. NO. 112628/5

SEEB INTERNATIONAL AIRPORT  
P.O. BOX 1058 SEEB AIRPORT - MUSCAT  
SULTANATE OF OMAN  
TELEX : 5424 OAV/SEEB ON  
CABLE : OMANAVN  
FAX :  
TEL. : 519286



الشركة العمانية لخدمات الطيران ش.م.ع.  
سجل تجاري رقم ١/١٢٦٢٨/٥

مطار السيب الدولي  
ص.ب : ١٠٥٨ مطار السيب - مسقط  
سلطنة عمان  
تلكس : ٥٤٢٤ أو. ا. اس. السيب أو إن  
برقيا : عمان افن  
فاكس :  
تليفون :

TO WHOMSOEVER IT MAY CONCERN

This will confirm that M/s Al Ansari Trading Enterprise LLC is carrying out the airconditioning works at our Aircraft Catering Unit at Seeb International Airport.

The work, costing approx. RO. 89,000, involves the replacement of two Air Handling Units of capacity 66 ton each, modification of chilled water pipes, modification of ductwork and replacement of entire existing insulation of approx 60,000 sq ft. This complex task required careful planning and coordination so as to ensure that catering operations were not disrupted while the modification were taking place.

We have no hesitation in recommending M/s Al Ansari Trading Enterprise LLC as reliable and an efficient Airconditioning Contractor.

This recommendation is issued at the request of the Contractor without any liability on the part of Oman Aviation.

Awad Banukhalef  
A/Divisional Manager - Fin & Admn

27 October 1992